1	ABSTRACT
2	A method for making UBM (Under Bump Metallurgy) pads and bumps on a wafer
3	is disclosed. Openings are formed in a photoresist layer for forming bumps, a positive
4	liquid photoresist is provided into the openings of the photoresist layer for forming
5	bumps. The positive liquid photoresist is exposed and developed to modify the
6	openings of the photoresist layer. Thus, bumps formed in the modified openings have
7	precise bonding areas on the UBM layer. Using the bumps as a mask, UBM pads under
8	the bumps are formed by etching the UBM layer, so that the reflowed bumps have an
9	uniform height.
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	